

## BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. 8820	LOCATION 808-36th			
DATE 10/27/31	PURPOSE Restored part of Reg 96 Terrace	PHONES		
ZONE 2-Fam	OWNER Iron Jewelry			
	ARCH'T			
	CONT-R C. H. Korman			
VAL. 850	STORIES	ROOMS	APTS.	SIZE
Light Shafts		Elevator Shafts		
Vent Shafts		Boiler Rooms		
Owner's Inspector		Sprinkler System		
Lath		Gas Vents		
Fire Escapes		Chimneys		
Stand Pipes		Skylights		

DATE	CONDITION OF WORK-REMARKS
10/27/31	Preliminary Insp. Contractors removing wood-lath & cement plaster on exterior of Dwyer Garage to replace same with 2 Shear Pldg Paper, 18-gauge wire and 3/8" Cement Plaster. Also Cutler Termite Control
	making repairs for termite damage. A.H. Campbell
11/2/31	Frame for repairs to 1st floor <sup>of Termite Damage</sup> OK A.H. Campbell
11/3/31	3 <sup>rd</sup> W.S.P. EXT LATH IN PLACE OK A.H. Campbell
	COMPLETE AND O.K. INSPECTOR