

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT No. <i>A-740</i>	LOCATION <i>5335 - W Street</i>
DATE <i>July 17, 53</i>	PURPOSE <i>Alterations &amp; Repairs to</i> PHONES <i>Level</i>
ZONE <i>27 am</i>	OWNER <i>Mrs E. Hartman</i>
	ARCH'T <i>Owner</i>
	CONT-R

VAL. <i>500<sup>00</sup></i>	STORIES <i>1</i>	ROOMS	APTS.	SIZE
------------------------------	------------------	-------	-------	------

Light Shafts	Elevator Shafts
Vent Shafts	Boiler Rooms
Owner's Inspector	Sprinkler System
Lath	Gas Vents
Fire Escapes	Chimneys
Stand Pipes	Skylights

DATE	CONDITION OF WORK—REMARKS
7/14/33	<p>2<sup>ND</sup>/NSP. Frame for Alterations &amp; Repair &amp; Demolition  Notified Owner that trouble of jacket chimney  in corner of room was located only 5" below  ceiling line and was dangerous and requested  Owner to have same lowered to not less than  18" below ceiling. Owner agreed to do so.</p>
7/20/33	<p>3<sup>RD</sup>/NSP. INT. PART FOR NEW PARTS. <i>A.W. Campbell</i>  <i>Ed Campbell</i></p>
8/7/33	<p>4<sup>TH</sup>/NSP. Alterations &amp; Repairs Completed.  Street Cleaned OK</p>
8/7/33	<p>COMPLETE AND O. K. <i>Allen Campbell</i> INSPECTOR</p>