

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>H-3932</i>	LOCATION <i>1100 - 4<sup>th</sup> St.</i>			
DATE <i>2/25/36</i>	PURPOSE <i>Alterations &amp; Repairs to Ball Grounds</i>			
ZONE <i>Gen. Retail.</i>	OWNER <i>St. Louis Cardinals</i>			
ARCH'T.	CONTR. <i>G. H. Griesentrog 2720 - 5<sup>th</sup> St.</i>			
VAL. <i>1000<sup>00</sup></i>	STORIES	ROOMS	APTS <input checked="" type="checkbox"/>	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK—REMARKS
2/25/36	Made Inspection of Grandstand accompanied by Fire Chief Sample. Gony to remove all decayed timbers and cables with saw.
	Also extend floor under Grandstand and
	Heath up to rest of Center Exit Runways
	in South Hall. Also Repair of <sup>OK</sup> PW Campbell
3/1/36	Made Partial Frame Job South Dining Rm. <sup>OK</sup> PW Campbell
3/10/36	" Bal of frame for Office addition. <sup>OK</sup> PW Campbell
3/16/36	Used Masonry + Cement for Office <sup>OK</sup> PW Campbell
3/20/36	2" MP LISP. Bal of frame including Reinforcement of Top chord of frame over Grandstand and junction between doors.
3/20/36	Set freight by storm; <sup>OK</sup> PW Campbell <div style="display: flex; justify-content: space-between;"> <span>COMPLETE AND O. K.</span> <span>INSPECTOR</span> </div>