

## BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>8.316</i>	LOCATION <i>1550 39<sup>th</sup> St.</i>
DATE <i>7/25/31</i>	PURPOSE <i>Gen Rep.</i>
ZONE <i>Stam.</i>	OWNER <i>Mrs. Geo. W. Lewis</i>
	ARCH'T <i>J. Maloney</i>
	CONT-R <i>J. Maloney</i>

VAL. <i>250</i>	STORIES	ROOMS	APTS.	SIZE
--------------------	---------	-------	-------	------

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK-REMARKS
7/27/31	Made Inspection of damage to building caused by Termites Found underpinning, and ends of joists.
8/3/31	Walls corners badly eaten away. Contractor turning out <del>2nd story</del> frame for repairs. All complete affected parts to be replaced with new materials.
	treated by Licensed Termites Control Insp. Al Campbell
7/27/31	Made Partial Frame Insp. Al Campbell
8/18/31	General Repairs to 2 Story Bldg. Completed.
8/18/31	COMPLETE AND O.K. Al Campbell INSPECTOR