

BUILDING DIVISION—BUILDING INSPECTOR:

TYPE VII BUILDINGS

PERMIT NO. <i>No CHANGE PERMIT</i>	LOCATION <i>531-35th St.</i>	
DATE <i>FEB. 26, 1931</i>	PURPOSE <i>Make Repairs to Tile Roof.</i>	ROOFING
ZONE <i>2-Family</i>	OWNER <i>HACKETT REALTY CO</i>	P 13 18
	ARCHT	
	CONT'R <i>MARTIN ROOFING CO</i>	
	VAL. <i>50.00</i>	STORIES <i>1</i>
		SIZE

FOUNDATION	STORY	BSMT	1	2	3	ROOF		
Ex Wall	Joints						Chimneys	Cellar Tanks
	Beams and Girders						Fire Place	
Int Wall	Studs and Columns						Gas Water Heater	
	Bridging Fire Stops						Heater Closet	
Piers	Fire Escape Stand Pipes						Furnace	Window Courts
	Metal Lath						Boiler Room	
	Stairs						Elevator Shaft	

DATE	CONDITION OR WORK—REMARKS
2/16/31	<p>Inspected Repairs to Tele Room. Observed Tile only lapped about $\frac{1}{2}$" - most holes exposed should have been at least 3" laps.</p> <p style="text-align: right;">Alden W Campbell</p>
2/16/31	<p>COMPLETED AND O.K.</p> <p style="text-align: center;">Alden W Campbell</p> <p style="text-align: right;">INSPECTOR</p>