

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-369-</i> DATE <i>4/16/38</i> ZONE	LOCATION	<i>1225 - 1 St.</i>
	PURPOSE	<i>Repairs due to termites</i>
	OWNER	<i>Agents Mowrey Co.</i>
	ARCH'T.	
	CONT'R.	<i>Dipray Moore</i>

VAL. <i>350⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE
------------------------------	---------	-------	-------	------

LIGHT SHAFTS	ELEVATOR SHAFTS
VENT SHAFTS	BOILER ROOMS
OWNER'S INSPECTOR	SPRINKLER SYSTEM
LATH	GAS VENTS
FIRE ESCAPES	CHIMNEYS
STAND PIPES	SKYLIGHTS

DATE	CONDITION OF WORK—REMARKS
4/18/38	<p>2ND / NSP. Frame for Repair to post, and Studs of cross wall in Basement damaged by Termites by wood in contact with ground. Decayed timbers replaced with new ones and bottom plate braced and all to be sprayed. O.K. W. H. Campbell</p>
4/18/38	<p>COMPLETE AND O. K. <i>Walter H. Campbell</i> INSPECTOR</p>