

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>B-40-</i>	LOCATION <i>1100 - U Street</i>			
DATE <i>3/8/38</i>	PURPOSE <i>Repairs to Ballfield due to storm</i>			
ZONE	OWNER <i>Cardinal Field</i>			
	ARCH'T.			
	CONT'R. <i>Jindrey - Swinerton</i>			
VAL. <i>25000<sup>00</sup></i>	STORIES	ROOMS	APTS.	SIZE

LIGHT SHAFTS	ELEVATOR SHAFTS
VENT SHAFTS	BOILER ROOMS
OWNER'S INSPECTOR	SPRINKLER SYSTEM
LATH	GAS VENTS
FIRE ESCAPES	CHIMNEYS
STAND PIPES	SKYLIGHTS

DATE	CONDITION OF WORK—REMARKS
3/8/38	1 <sup>ST</sup> INSP. Concrete Piers for Bleacher Roof Posts O. K. M. W. Campbell
3/11/38	2 <sup>ND</sup> INSP. Rooster Frame in Repair to Grand Stand
3/15/38	2 <sup>ND</sup> INSP. " " " Roof Trusses } OK
3/18/38	2 <sup>ND</sup> INSP. " " " Ramp Approach } M. W. Campbell
3/22/38	2 <sup>ND</sup> INSP. " " " Bleacher Roof. } M. W. Campbell
3/24/38	2 <sup>ND</sup> INSP. Bal of Frame for entire job. OK M. W. Campbell
3/24/38	COMPLETE AND O. K. Alden W. Campbell INSPECTOR