

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-2878</i>	LOCATION <i>1123-10th St.</i>
DATE <i>5/31/35</i>	PURPOSE <i>General repairs to fixtures</i>
ZONE <i>Gen. Com.</i>	OWNER <i>Warner Bros.</i>
	ARCH'T <i>Elton Blair</i>
VAL. <i>3800⁰⁰</i>	STORIES
	ROOMS
	APTS.
	SIZE

Light Shafts	Elevator Shafts
Vent Shafts	Boiler Rooms
Owner's Inspector	Sprinkler System
Lath	Gas Vents
Fire Escapes	Chimneys
Stand Pipes	Skylights

DATE	CONDITION OF WORK—REMARKS
5/30/35	Made Partial Insp of Damage by Fire & Roof Timbers in Court Hall. A.W. Campbell
6/28/35	2 ND Insp. Partial Frame. Found Roof Truss Timbers only charred. After cleaning up with steel braches said timbers are still larger in size (originally rough) than if new and aged. Contractor will bolt timbers to side of top & bottom chords & brace in a few places that were damaged more than rest of the above members. A.W. Campbell
	COMPLETE AND O. K. INSPECTOR