

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-279</i>	LOCATION <i>3432 - 38th St.</i>		
DATE <i>5/7/35</i>	PURPOSE <i>Repairs to dwel</i>	PROCES	
ZONE	OWNER <i>H. Gladney</i>		
	ARCH'T		
	CONT'R <i>Chas Varina</i>		
VAL. <i>500⁰⁰</i>	STORIES	ROOMS	APTS.
			SIZE
Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK-REMARKS
5/7/25	Made Inspector's Reports to rear part of bridge damaged by fire.
	All burned timbers etc replaced with good material. O.K. AW Campbell
	<div style="display: flex; justify-content: space-between;"> COMPLETE AND O. K. INSPECTOR </div>