

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>A-5261</i>	LOCATION <i>1225- Robertson Way</i>
DATE <i>11/18/36</i>	PURPOSE <i>Erect new dwls</i>
ZONE <i>—</i>	OWNER <i>Land Dr. Tenack, Inc.</i>
	ARCH'T. <i>W. H. Murcell</i>
	CONTR. <i>W. H. Murcell</i>

VAL. <i>65000<sup>00</sup></i>	STORIES	ROOMS	APTS.	SIZE
--------------------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
11/19/36	1 <sup>ST</sup> /NSP. Form in place <sup>OK</sup> HW Campbell
12/12/36	2 <sup>ND</sup> /NSP. Frame . . . . . <sup>OK</sup> HW Campbell
12/30/36	3 <sup>RD</sup> /NSP. INT. LATH . . . . . <sup>OK</sup> HW Campbell
12/24/36	3 <sup>RD</sup> /NSP. EXT. LATH . . . . . <sup>OK</sup> HW Campbell
COMPLETE AND O. K.	INSPECTOR