


BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. 9583 DATE: 6/16/32 ZONE Itan	LOCATION 2157+36
	PURPOSE Rep Fire Loss - Add 2" Insulation - Bank
	OWNER L.R. Painter
	ARCH'T
	CONT-R Owner

VAL.	2000	STORIES	ROOMS	APTS.	SIZE
------	-------------	---------	-------	-------	------

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK--REMARKS OK
7/14/37	2 ND INSP (PARTIAL FRAME FOR 9" Sky Addition) All Complete
8/2-32	2. Insps Frame of R/R Rectors
8/10-32	3 " Insps Sath of R/R Rectors
1/9-33	4 " Insps and OK
	<div style="display: flex; justify-content: space-between; align-items: center;"> COMPLETE AND O. K. <div data-bbox="546 916 1224 1072" style="text-align: center;">  </div> INSPECTOR </div>