

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. B-563	LOCATION 1630 - Mt			
DATE 5/9/38	PURPOSE Repairs to dwg due to storm			
ZONE	OWNER J. H. McQuistion -			
	ARCH'T. J. F. Gould			
	CONTR. J. F. Gould			
VAL. 1600²	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK—REMARKS
5/13/38	1 st / NSP Repairs & Quick Foundation when July was damaged by big storm & falling trees in Feb. 9 th 1938 - R. W. Campbell
5/27/38	2 nd NSP (Part 200) For B... W... R. W. Campbell
6/7/38	2 nd NSP Bell Frame OK R. W. Campbell
	<p data-bbox="306 888 439 930">COMPLETE AND O. K.</p> <p data-bbox="1188 907 1321 928">INSPECTOR</p>