

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPES I, II, III, IV, V, VI BUILDINGS

PERMIT NO. 5041	LOCATION S 1/2 Cor 5th & 15th St	PHONES 503-11016
DATE 8/29/29	PURPOSE Bank Bldg	OWNER Security Investment Co. 517 J.
ZONE	ARCH'T H. J. ...	CONTR ...

VAL. 45000	STORIES	ROOMS	APTS.	SIZE
----------------------	---------	-------	-------	------

Steel Tested by		Elevator Shafts	
Cement Tested by		Boiler Rooms	
Owner's Inspector Rfd. Conc.		Sprinkler System	
Fire Escapes		Floor Tests	
Stand-pipes			

DATE

CONDITION OF WORK—REMARKS

7/31/29	1 Box Lath in place — OK R. H. Reuter
8/4/29	2 Insp Int Lath OK R. H. Reuter
10/31/29	Finalled & found OK R. H. Reuter Certificate of Occupancy issued Street cleaned up

 COMPLETED
AND O. K.

R. H. Reuter

INSPECTOR