

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-3173</i>	LOCATION <i>2540-9TH AVE.</i>			
DATE <i>Aug 17 1935</i>	PURPOSE <i>Erect 1 1/2 St. Fr. Brick - Veneer 5 Rm. Dwell & Garage</i>			
ZONE <i>2-Family</i>	OWNER <i>FRANK GILLENWATER</i>			
	ARCH'T.			
	CONT'R. <i>C-C-RUBY</i>			
VAL. <i>4000⁰⁰</i>	STORIES <i>1</i>	ROOMS	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK—REMARKS
8/20/35	1 st /NSP. Forms in place ^{OK} A W Campbell
9/6-35	2 nd Scaff Frame of R H Reuter
9/12.	3 " Scaff " Reuter
1-21-36	Cannot find as there has never been
	installed a guard rail at the rear of
	the back door. ^{trap door} As the cement floor
	is only 3 ft wide and opens on basement
	trap door. Have notified builder and
	<p>COMPLETE ^{also owner} AND O. K.</p> <p>R H Reuter INSPECTOR</p>