

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A 6311</i> DATE <i>5/13/37</i> ZONE	LOCATION	<i>826 - 8 St.</i>
	PURPOSE	<i>Remodel front</i>
	OWNER	<i>El Florado Cafe.</i>
	ARCH'T.	
	CONTR.	<i>Frank Maloney</i>

VAL. <i>500.00</i>	STORIES	ROOMS	APTS.	SIZE
--------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
4/21/37	<p>Made Precursor Inspection of front fire walls and lintel of Hdq. Found lintel to be of wood built-up supporting brick fire wall contrary to Bldg. Code. Notified Owner. Steel I Beam would be required to be installed. brick fire wall removed and new fire wall built above same. Owner let contract to this contractor to do so.</p>
5/13/37	<p>Work Completed including T.V. Facing on front of Hdq. O.K.</p>
6/13/37	<p>COMPLETE AND O. K. <i>Allen W. Campbell</i> INSPECTOR</p>