

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>D-6101-</i>	LOCATION <i>409 - J St -</i>
DATE <i>4/12/37</i>	PURPOSE <i>Remodel floor front</i>
ZONE	OWNER <i>R. Hatch -</i>
	ARCH'T.
	CONT'R. <i>Chas Vanina -</i>

VAL. <i>2000</i>	STORIES	ROOMS	APTS.	SIZE
------------------	---------	-------	-------	------

LIGHT SHAFTS	ELEVATOR SHAFTS
VENT SHAFTS	BOILER ROOMS
OWNER'S INSPECTOR	SPRINKLER SYSTEM
LATH	GAS VENTS
FIRE ESCAPES	CHIMNEYS
STAND PIPES	SKYLIGHTS

DATE	CONDITION OF WORK—REMARKS
<p>4/17/37 4/27/37</p>	<p>2<sup>ND</sup>/NSP. Frame for Remodeling interior &amp; front entrance to 3-Story Brick Hotel Bldg. Hall ceilings framed same for Air Cond. cooling system.</p> <p>O.K. - A.W. Campbell</p>
<p>4/29/37</p>	<p>3<sup>RD</sup>/NSP. INT. LATH. Used 3/8" Plaster sand plaster on new walls &amp; ceilings of hall.</p> <p>O.K. A.W. Campbell</p>
<p>5/17/37</p>	<p>4<sup>TH</sup>/NSP. Remodeling of Hotel Complete</p>
<p>5/17/37</p>	<p>COMPLETE AND O. K. <i>Alden W. Campbell</i> INSPECTOR</p>