

R244 F5-13

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$61.00

TYPE BUILDINGS R251 F113 File

PERMIT NO. <b>G-1171</b>	LOCATION <b>1009 - 9th Street A-2 (10)</b>
DATE <b>Aug. 9-68</b>	PURPOSE <b>Remodel 1st &amp; 2nd floor of office bldg</b>
ZONE <b>C-3</b>	OWNER <b>Mr. Fahn 1925 - 13th Avenue</b>
	ARCH'T <b>E. J. Taylor - Sacto.</b>
	CONT'R <b>J. C. Sparks 7432-Loma Verde Way</b>

VAL. <b>\$17,100.</b>	STORIES	ROOMS	APTS.	SIZE
-----------------------	---------	-------	-------	------

INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	PHONE (OL) (C)
		<b>V-1 hr.</b>	<b>F-2</b>	<b>421-8775</b>
FORM	<b>9-12-68</b>	<b>Larsen</b>		
JOIST				
FRAME	<b>9-5-68</b>	<b>Larsen</b>		
SHEET ROCK	<b>9-11-68</b>	<b>Larsen</b>		
FINAL	<b>10/14/68</b>	<b>C. Thompson</b>		<b>Int.</b>

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
8-27-68	All sections must be indicated. Services in wall below footing must be exposed per notes. (brick) must be re-encased. Same.
9-4-68	Put braces on wall. Fill holes in adjacent walls. etc. inculcated. Same.
9-16-68	OK 7' B.B. Chopin
9-11-68	OK. slab vault floor Harmono
9-20-68	OK. steel for vault - photo 9-20-68 OK B.B. Rich.
	COMPLETE AND OK <span style="float: right;">INSPECTOR</span>

