

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD					\$13.50
TYPE BUILDINGS					<i>H-80</i> <i>F-131</i>
PERMIT NO. D-7816	LOCATION 2276 - Pierre Avenue				A-5
DATE Feb. 20-61	PURPOSE Repair explosion damage to dwelling.				
ZONE R-1	OWNER State Savings & Loan				Stockton, Cal
	ARCH'T				IV 9-9568
	CONT'R Ted. F. Merrill 2524-Tesla Way				
VAL. \$4,000.	STORIES	ROOMS	APTS.	SIZE	
INSP.	DATE		INSPECTOR		
FORM					
JOIST					
FRAME	<i>3-6-61</i>	<i>Barlato</i>			
LATH	<i>3-14-61</i>	<i>Barlato</i>			
FINAL	<i>8-4-61</i>	<i>Benny</i>			

DATE	SPECIAL CONDITIONS OF WORK—REMARKS
2-24-61	P.T. Not ready for frame insp. Backate
3-3-61	P.T. Bldg locked. No frame insp. Backate
3-8-61	P.T. Re-nail ceiling in kitchen and dining areas with approved S R nails. Hubler
4-15-61	P.T. Bldg locked, unable to make insp. Backate
	<p data-bbox="310 879 462 933">COMPLETE AND OK</p> <p data-bbox="1268 906 1428 933" style="text-align: right;">INSPECTOR</p>