

CITY OF SACRAMENTO

CERTIFICATE OF OCCUPANCY

This Building, the address of which is 1040 Florin Road (Luckys),
Sacramento, California, is hereby classified as a Group B-2 Occupancy, to wit:
Interior Remodel, and is of Type _____

Construction as defined in the Sacramento City Building Code. It has been constructed and completed in accordance with the requirements of the Sacramento City Building Code and, where applicable, with the requirements of the State Laws.

Therefore, as of this date February 27, 1990, it is hereby Certified for the Occupancy described above and may be occupied.

PERMIT NO.: T-1257-C

OWNER: Lucky Soores Inc.

**Post in a
Conspicuous Place**

(over)

D.T. SULLIVAN, SUPERINTENDENT
Building Inspections Division

by: [Signature]
Beals Building Inspector