

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B. 10595</i>	LOCATION <i>1230 P. ST.</i>
DATE <i>8/11/42</i>	PURPOSE <i>Make General Repairs to Fire Loss</i>
ZONE <i>Multifam</i>	OWNER <i>L. G. SILLER</i>
	ARCH'T.
	CONTR. <i>CHAS. L. VANINA</i>

VAL.	STORIES	ROOMS	APTS.	SIZE
------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
8/20/42	2 <sup>ND</sup> Insp - Frame for Reconstructed Roof recently damaged by fire. All burned timbers replaced with new materials O.K. A.W. Campbell
	COMPLETE AND O. K. <span style="float: right;">INSPECTOR</span>