

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-2940</i>	LOCATION <i>723 - 1st</i>			
DATE <i>3/19 '37</i>	PURPOSE <i>Repairs to Bldg. Fire Loss</i>			
ZONE <i>Gen Com.</i>	OWNER <i>Robert T. Hooplin</i>			
	ARCH'T.			
	CONTR. <i>Frank Maloney, 3172-T</i>			
VAL. <i>14000⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE

LIGHT SHAFTS	ELEVATOR SHAFTS
VENT SHAFTS	BOILER ROOMS
OWNER'S INSPECTOR	SPRINKLER SYSTEM
LATH	GAS VENTS
FIRE ESCAPES	CHIMNEYS
STAND PIPES	SKYLIGHTS

DATE	CONDITION OF WORK—REMARKS
4/10/37	2 ND INSP. Part Frame for New 1 ST Floor Joists & Sills. <i>OK</i> All Campbell
4/17/37	2 ND INSP. " " " Roof. <i>OK</i> All Campbell
5/10/37	2 ND INSP. End of Frame. <i>OK</i> All Campbell.
5/10/37	3 RD INSP. INT. LATH. Max plates direct to brick walls. <i>Used 3/8" Sup. Lath on Ceiling.</i>
	<div style="display: flex; justify-content: space-between;"> COMPLETE AND O. K. INSPECTOR </div>