

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

| | |
|-----------------------------|---|
| PERMIT NO. <i>B-3967</i> | LOCATION <i>508 1/2 W</i> |
| DATE <i>10/3/39</i> | PURPOSE <i>Gen. Repairs to stone -</i> |
| ZONE | OWNER <i>Fisher Estate.</i> |
| | ARCH'T. |
| | CONT'R. <i>Chas. Varina -</i> |

| | | | | |
|-------------------------------|---------|-------|-------|------|
| VAL. <i>2900⁰⁰</i> | STORIES | ROOMS | APTS. | SIZE |
|-------------------------------|---------|-------|-------|------|

| | | | |
|-------------------|--|------------------|--|
| LIGHT SHAFTS | | ELEVATOR SHAFTS | |
| VENT SHAFTS | | BOILER ROOMS | |
| OWNER'S INSPECTOR | | SPRINKLER SYSTEM | |
| LATH. | | GAS VENTS | |
| FIRE ESCAPES | | CHIMNEYS | |
| STAND PIPES | | SKYLIGHTS | |

| DATE | CONDITION OF WORK—REMARKS |
|--------------------|---|
| 10/3/39 | Made Partial Inspection of room & hallway on 2 nd floor. Room removed by fire. A.W. Campbell |
| 10/4/39 | 2 nd floor NSP. Frame fracture. A.W. Campbell |
| 10/4/39 | 3 rd floor NSP. Patching, lathing. A.W. Campbell |
| | |
| | |
| | |
| | |
| | |
| COMPLETE AND O. K. | INSPECTOR |