

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPES I, II, III, IV, V, VI BUILDINGS

PERMIT NO. <i>6081</i>	LOCATION <i>Parcel of Council 4/3/30</i>	PHONES <i>2130 9</i>
DATE <i>4/1/30</i>	PURPOSE <i>Steel, Glass Service Station</i>	
ZONE	OWNER <i>Mrs J B Resnick</i>	
	ARCH'T	
	CONT'R <i>Owner</i>	

VAL. <i>4900</i>	STORIES	ROOMS	APTS.	SIZE
---------------------	---------	-------	-------	------

Steel Tested by		Elevator Shafts	
Cement Tested by		Boiler Rooms	
Owner's Inspector Rfd. Conc.		Sprinkler System	
		Floor Tests	
Fire Escapes			
Stand Pipes			

DATE	CONDITION OF WORK—REMARKS
4/6/30	1 <sup>ST</sup> /ISP. Forms for Service Station. OK Campbell
5/4/30	2 <sup>ND</sup> /ISP. Forms. Steel Service Station. 8' Tile Wall on 2 sides on accessory Bldg. OK Campbell
	No Lath or Plastering.
5/4/30	Approaches installed <sup>as per permission</sup> City Council OK Campbell
5/14/30	4 <sup>TH</sup> /ISP. Service Station OK Campbell
	ISSUED CERTIFICATE OF OCCUPANCY #6081
	Street Cleaned up OK Campbell
5/14/30	COMPLETED AND O.K. <i>Allen H Campbell</i> INSPECTOR