

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPES I, II, III, IV, V, VI BUILDINGS

PERMIT NO. <i>6183</i>	LOCATION <i>1131 1/2</i>			
DATE <i>4/25/20</i>	PURPOSE <i>Change out windows</i>	PHONES		
ZONE	OWNER <i>Mission Temple Assoc.</i>			
	ARCH'T			
	CONT'R <i>Gambell Construction</i>			
VAL. <i>1701</i>	STORIES	ROOMS	APTS.	SIZE

Steel Tested by		Elevator Shafts	
Cement Tested by		Boiler Rooms	
Owner's Inspector Rfcd. Conc.		Sprinkler System	
		Floor Tests	
Fire Escapes			
Stand Pipes			

DATE	CONDITION OF WORK—REMARKS
4/28/30	Partial Insp. of Remodeling, Rybeers. Vault
	formerly used by Bank of Holy Branch, several
	part of Corner Store to be changed and partitioned
	part back in center dividing into 2 stores.
	A.W. Campbell
	<div style="display: flex; justify-content: space-between;"> COMPLETED AND O.K. INSPECTOR </div>