


BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B 5478</i>	LOCATION <i>1120 - 6th St.</i>			
DATE <i>6/16/41</i>	PURPOSE <i>Erect new dwelling</i>			
ZONE	OWNER <i>Volunteers American</i>			
	ARCH'T.			
	CONTR. <i>A. J. Fisher - 802-359</i>			
VAL. <i>7600</i>	STORIES <i>1</i>	ROOMS	APTS.	SIZE

LIGHT SHAFTS	ELEVATOR SHAFTS
VENT SHAFTS	BOILER ROOMS
OWNER'S INSPECTOR	SPRINKLER SYSTEM
LATH	GAS VENTS
FIRE ESCAPES	CHIMNEYS
STAND PIPES	SKYLIGHTS



DATE	CONDITION OF WORK-REMARKS
6/23/41	1 st flsr. Footings for Re-Inf. Conc Found. ^{OK} A.W. Campbell
7/24/41	1 st flsr. Basement Wall Form. ^{OK} A.W. Campbell
	Note. Contractor changed thickness of Basement Walls from 8" to 12" and omitted Re Inf Steel because he was unable to obtain steel. This was done on approval of Architect: A.W.C.
7/30/41	2 nd flsr. Part frame (Basement): A.W. Campbell
9/4/41	3 rd flsr. Part frame for walls only to be placed
10/26/41	Ceiling left unplaned. A.W. Campbell 4 th flsr. Part frame completed. ^{OK}
10/26/41	COMPLETE AND O. K. <i>Allen W Campbell</i> INSPECTOR