

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>8028</i>	LOCATION <i>1632 - 42<sup>nd</sup> St</i>
DATE <i>5/14/31</i>	PURPOSE <i>Addn &amp; Repair to Inf.</i>
ZONE <i>2 Fam.</i>	OWNER <i>J P Hawthorne</i>
	ARCH'T <i>[Signature]</i>
	CONT-R <i>[Signature]</i>

VAL. <i>250-</i>	STORIES <i>1</i>	ROOMS	APTS.	SIZE
---------------------	---------------------	-------	-------	------

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK-REMARKS
5/15/31	1 <sup>ST</sup> / NSP. Formis for Rear Porch Addition OK A.W. Campbell
5/19/31	Notified Owner to install 3 Vents below floor <sup>as requested by H.A.</sup> A.W. Campbell 2 <sup>ND</sup> / NSP. Frame for Addition OK A.W. Campbell Note - Owner will install 3 Vents as requested A.W. Campbell
5/19/31	INT WALLS & CEILING OF ADDITION TO BE T. & G.
7/7/31	4 <sup>TH</sup> / NSP. Addition to Dwlg Completed OK
7/7/31	COMPLETE AND O.K. <i>Alden H. Campbell</i> INSPECTOR