

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. 5506-	LOCATION 418 - K St -			
DATE 1/13/37	PURPOSE Alter, Repair, Finishes			
ZONE Gen Com	OWNER Woolworth Stores Inc -			
	ARCH'T. McDonald & Kahn			
VAL: 15000 ⁰⁰	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK-REMARKS
4/15/37	2 ND INSP. Frame for 2 ND STY REAR PART OF BLDG
	All damaged Timbers replaced with new. A.W. Campbell
4/18/37	3 RD INSP. INT. Metal Lath Curtains replaced on each
	side of 2 ND Sty. Eaves ^{OK} A.W. Campbell
4/20/37	2 ND INSP. Frame for 3 RD STY ^{140 STEEL COL. + BEAMS} NOT REFERRED TO ORIGINAL
	Condition including New Work. A.W. Campbell
4/27/37	3 RD INSP. INT LATH 3 RD STY REAR PART ^{OK} A.W. Campbell
2/11/37	4 TH INSP. Repairs for Fire Loss Completed OK
2/11/37	COMPLETE AND O. K. <i>Allen W. Campbell</i> INSPECTOR

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. 5506-	LOCATION 718 - RPT -			
DATE 1/13/37	PURPOSE Alley Repairs Fireproof			
ZONE rescom	OWNER Woolworth Stores Inc			
	ARCH'T. McDonald & Kahn			
CONT'R.				
VAL. 15,000 ⁰⁰	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK-REMARKS
4/15/37	2 ND INSP. Frame for 2 ND STY REAR PART OF BLDG
	All burned Timbers replaced with New. A.W. Campbell
4/18/37	3 RD INSP. INT. Metal Lath Ceiling replaced on each side of 2 ND Sty. Ceiling ^{OR} A.W. Campbell
4/20/37	2 ND INSP. Frame for 3 RD STY PART REFERRED TO ORIGINAL ^{INC. STEEL COL. & BEAMS} Condition including New Part. A.W. Campbell
4/27/37	3 RD INSP. INT LATH 3 RD STY rear part ^{OR} A.W. Campbell
2/11/37	4 TH INSP. Repairs for Fire Loss Completed OK
2/11/37	COMPLETE AND O. K. <i>Alfred W. Campbell</i> INSPECTOR