

BUILDING DIVISION - BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>9652</i>	LOCATION <i>3106 - 72 St</i>	
	PURPOSE <i>New Addition to New Tenement</i>	PHONES
DATE <i>6/27/32</i>	OWNER <i>R P Miles</i>	
ZONE <i>Middle ten</i>	ARCH'T	
	CONT-R <i>Owner</i>	

VAL. <i>2400</i>	STORIES <i>2</i>	ROOMS	APTS.	SIZE
---------------------	---------------------	-------	-------	------

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK—REMARKS	
4/5/32	1 st / ASP Frame for New Foundation under & side rd dwlg. OK	A.W. Campbell
4/20/32	2 nd / ASP Frame for new underpinning for DWlg.	O.K. A.W. Campbell
4/24/32	4 th / ASP. Repairs to Foundation Completed	OK A.W. Campbell
7/20/32	COMPLETE AND O.K.	Inspector A.W. Campbell