AMENDED REPORT (See Back Page)

Architecutral Review Board Sacramento, Câlifornia

Members in Session:

SUBJECT: Sign Review for Bay View Federal Savings and Loan Building

LOCATION: Southeast corner of Alhambra Boulevard and "J" Street

BACKGROUND INFORMATION

On April 4, 1979, the ARB approved a two-story savings and loan building subject to the following conditions:

- 1. The monument sign shall be reviewed and approved by the ARB;
- 2. A detailed landscape-irrigation plan shall be submitted to staff for review and approval.

The landscape plan has been approved by the staff and the City Landscape Architect. The sign, however, has not been approved. The preliminary design of the monument sign consisted of an identification-logo sign that was 3'8% X 4'11" and located on the corner of the lot (Alhambra and "J" Street corner).

The sign proposal was resubmitted for ARB review on September 5, 1979. However, the staff recommended continuance so the applicant could redesign and reduce the height of the sign. Subsequently, the proposal has been continued for three meetings at the request of the applicant.

At the November 7, 1979 ARB meeting, the Board continued this item to the November 14, 1979 meeting inorder for the applicant to submit detailed plans.

SIGN PROPOSAL:

The applicant proposes to install a monument type sign to identify "Bay View Federal Savings" of Alhamnra Boulevard and "J" Street.

This wign would be 3'8" X 4'11" in size and $5\frac{1}{2}$ feet in height (See attached elevations). The sign is the company's standard logo-identification sign that is red, blue and gold color. This same sign was approved by the ARB, to be located on the south wall of the subject building.

STAFF EVALUATION

The staff has reviewed the sign proposal and has the following comments:

- 1. Staff has no objection to the size and height of the proposed sign.
- 2. The sign as proposed appears to be a pole sign and not a monument sign. Staff suggests a box or pedestal be designed under and around the sign so that it would appear as a monument sign. This material should be stucco or wood to complement the building materials.

3. Staff has concerns as to the location of the monument sign. The City Traffic Engineer was requested to review the sign location relative to any potentiallyisual problems for the motorist. Comments will be presented at the Board meeting. An alternative would be to locate the sign perpendicualr to the building and approximately 8 feet from the "J" Street property line.

STAFF RECOMMENDATION

Staff recommends approval of the monument sign subject to the following conditions:

- 1. A box or pedestal shall be designed under the proposed sign. This material shall consist of wood or stucco to compliment the structure.
- *2. The monument sign shall be located perpendicular to the structure and be set back approximately 8 feet from the north property line.

Findings of Fact

1. The proposed sign complies with the Sign Ordinance.

bilmar


2. The proposed sign is compatible to the structure and surrounding properties.


Respectfully submitted,


Wilfred Weitman Associate Planner

WW:dd


* DELETE











BREV. 11-1-79 - D/F LOW PROFILE STANDARD FRANCIS PLEY
INSTALLED AT 45° AS SHOWN ON PLOT PLAN















SOUTH ELEVATION



ABC.

24" LTRS. PML.INT. ILLUM WHITE PLEX FACES POLISHED GOLD MTL RETURNS

DINGLE FACED SHIELD 3-8×4'-11"
FORMED PLEX INTILLUM
GOLD BLUE RED & WHITE
CAB POLISHED GOLD PML

(F) DE DISPLAY FORMED PLEX

INTILLUM DISPLAY WAS DAY 45°

AT CORNER DE ALHAMBRA É TEIS

SK

#/