

R272 - F297-299

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$23.00

TYPE BUILDINGS

PERMIT NO. G-5272		LOCATION 1488 - 33rd Street		A-1 (15)	
DATE Dec. 4-69		PURPOSE Const. 1-room addition to dwelling			
ZONE R-1		OWNER Russell Erfert		Same	
		ARCH'T			
		CONTR Owner		455-7448	
VAL. \$2,200.		STORIES	ROOMS	APTS.	SIZE 152 sq.ft.
INSP.	DATE	BLDG. TYPE		OCCUPANCY GROUP	PHONE (O) (C)
FORM	12-5-69	1st floor only 2/10/74		ED	
JOIST	1-26-70	Count		ED	
FRAME SHEET ROCK	3-26-71	Rold		2nd floor only 2/27/74	ED
FINAL					

111010, 111011, 111012, 111013, 111014, 111015, 111016, 111017, 111018, 111019, 111020, 111021, 111022, 111023, 111024, 111025, 111026, 111027, 111028, 111029, 111030, 111031, 111032, 111033, 111034, 111035, 111036, 111037, 111038, 111039, 111040, 111041, 111042, 111043, 111044, 111045, 111046, 111047, 111048, 111049, 111050, 111051, 111052, 111053, 111054, 111055, 111056, 111057, 111058, 111059, 111060, 111061, 111062, 111063, 111064, 111065, 111066, 111067, 111068, 111069, 111070, 111071, 111072, 111073, 111074, 111075, 111076, 111077, 111078, 111079, 111080, 111081, 111082, 111083, 111084, 111085, 111086, 111087, 111088, 111089, 111090, 111091, 111092, 111093, 111094, 111095, 111096, 111097, 111098, 111099, 111100

DATE	SPECIAL CONDITIONS OF WORK—REMARKS
12-4-70	Working, slow 12-4-70 Williams
1-30-71	slow - still working 12-3-70 Cole
2-5-71	can't permit - no progress Cole
1-21-74	P.L. no progress - send 1st notice of appeal
2/22/74	Plumer says he would start work on project above - S.F. to 3/11/74 Lane
3-11-74	S.P. 3-14-74 Jansen
COMPLETE AND OK	INSPECTOR