

*10327E309*

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$18.00**

**TYPE BUILDINGS**

<b>PERMIT NO.</b>					
<b>H-6479</b>	<b>LOCATION</b>	<b>1408 - 34th Avenue</b>			<b>A-3</b>
<b>DATE</b>	<b>PURPOSE</b>	<b>Reroof dwelling</b>			
<b>Apr. 25-72</b>	<b>OWNER</b>	<b>Harry Sato Same</b>			
<b>ZONE</b>	<b>ARCH'T</b>				
<b>R-1</b>	<b>CONT'R</b>	<b>Pioneer Rfg. Co. P.O. Box 191 W.S.</b>			
<b>VAL.</b>	<b>\$1,400.</b>	<b>STORIES</b>	<b>ROOMS</b>	<b>APTS.</b>	<b>SIZE</b>
				<b>36</b>	
<b>INSP.</b>	<b>DATE</b>	<b>BLDG. TYPE</b>	<b>OCCUPANCY GROUP</b>	<b>PHONE (O) (C)</b>	
				<b>443 4118</b>	
<b>FORM</b>					
<b>JOIST</b>					
<b>FRAME</b>					
<b>SHEET ROCK</b>					
<b>FINAL</b>	<i>3 28 73</i>	<i>Dana Fuller</i>			

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
COMPLETE AND OK	INSPECTOR