

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

| | | | | | | | | | |
|---------------------------------|--------------|---------------|-----------------------|--------------|----------------|-------------------------|--------------------------|-------------------|--|
| PROPERTY PARCEL NO. | | JOB ADDRESS | | | | | INSPECTION AREA | FINAL INSPECTIONS | |
| | | 3391 Lanatt | | | | | 1 | | |
| LEGAL DESCRIPTION | | OCCUP. GR. | CONST. EXEMPT | PAR. NO. | FIRE ZONE | BUILDING BY | | DATE | |
| Plat of Morlan Property St. | | | | | | Biolo | | 1/26/62 | |
| TITLE AND NAME | | 1/C | ADDRESS | | ZIP | CITY LIC. NO. | ELECTRICAL BY | | |
| Owner | | | Fort Lauderdale, Fla. | | | | DATE | | |
| GEN. CONTR. | | | | | | | PLUMBING BY | | |
| ELEC. CONTR. | | | | | | | DATE | | |
| PLBG. CONTR. | | | | | | | MECHANICAL BY | | |
| MECH. CONTR. | | | | | | | DATE | | |
| ARCH. ENGR. | | | | | | | CERTIFICATE OF OCCUPANCY | | |
| OWNER L.B. Jackson & R.H. Edney | | | | | | | ISSUED BY | | |
| CONST. LOAN LENDER | | | | | | | DATE | | |
| BLDG. WIDTH | BLDG. LENGTH | TOTAL HEIGHT | NO. OF STORIES | ROOF CONSTR. | AREA 1st FLOOR | TOTAL AREA | C.S.D. | C.I. CASE | |
| | | | 1 | | | 34,700 | | | |
| SIDE YARDS | REAR YARDS | SET BACK REQ. | USE ZONE | PARK'G REQ. | SPACES | PERCENT BLDG'G SAME LOT | CENSUS TRCT. NO. | HOW USED | |
| | | | | | | | | | |

B-2 DL N.H. Sprink

NATURE OF WORK:- Const. new laundry

| | | |
|--------------------------|--------------------------|--|
| PERMIT NO. S.P. - D-8192 | MICROFILM RECORD | |
| ISSUED BY | PLANS AND APPLICATION | REEL NO. R226 FRAME NO: P521 TO letter |
| ISSUANCE DATE 4/4/61 | INSPECTION RECORD | REEL NO. P51 FRAME NO: P546 TO 661 |
| VALUATION \$ 250.00 | JOB FILE | REEL NO. P566 FRAME NO: P52 - (copy) |
| R.D.F. FEE \$ | | |
| S.M.J. FEE \$ | | |
| PLAN CK. FEE \$ | | |
| SEWER INCL. FEE \$ | | |
| PERMIT FEE \$ 193.50 | REMARKS AND/OR VARIANCES | |
| \$ | Laundry | |
| \$ | | |
| TOTAL FEES \$ | | |

R 1098F221

RECORD OF SUBSEQUENT PERMITS ISSUED

| DATE | TYPE OF PERMIT AND VALUATION | PERMIT NO. AND FEE | NATURE OF WORK | PRESENT OWNER AND ADDRESS | CONTRACTOR & ADDRESS | FINALED BY DATE |
|------------------------------|------------------------------|---------------------|---|---------------------------|--------------------------|---|
| 9/2/76 | B. \$900.00 | D-6958 \$ 30.00 | Reeroof | National Linen Service | Hester Roofing | NO FINAL INSPECTION CALLED BY PERMITEE. |
| 9/11/67 | B. \$ 63,000 * | F-8420 \$ 164.00 | Const. addition on laundry | Jackson & Edney | Box 20195 | NO FINAL INSPECTION CALLED BY PERMITEE. |
| 12/15/76 | M.P.E. \$ 50,000 | 00 D-9824 \$ 344.50 | Installation of stand-by oil fired boiler in existing boiler room Atlanta | Ft. Lauderdale Fla Same | Owner | NO FINAL INSPECTION CALLED BY PERMITEE. |
| 4/11/79 | P. \$ 800.00 | G-3058 \$ 30.00 | Medium pressure gas line for steam boilers.-Comm | National Linen Serv. | Owner | NO FINAL INSPECTION CALLED BY PERMITEE. |
| 9/13/78 | E. \$1500 | F8697 \$42.50 | install temp. 1200 AMP/ Disc. to exis. serv. Comm. | National Linen | Reliable Elec. McDownell | 10/23/78 |
| 10/4/78 | E. \$1100 | F9554 \$176 | remove existing 1200 amp main service panel & ewplac w/ 2000 amp main service w/ seperation partition Comm. | National Linen | Yancey Co. | NO FINAL INSPECTION CALLED BY PERMITEE. |
| 6/19/78 | B. \$7100 | F5542 \$113 | reeroof Comm. | National Linen | Yancey Co. PO Box 160087 | NO FINAL INSPECTION CALLED BY PERMITEE. |
| 5/23/79 | E. \$200 | G4730 \$20 | connect gasoline pump Comm. | National Linen | owner | NO FINAL INSPECTION CALLED BY PERMITEE. |
| * Area Added total 44,000.00 | | | | | | |

MICROFILM RECORD

| PERMIT NO. | REEL AND FRAME NOS. | PERMIT NO. | REEL AND FRAME NOS. | PERMIT NO. | REEL AND FRAME NOS. |
|------------|---------------------|------------|---------------------|------------|---------------------|
| D-6958 | R4555R092 | F9554 | R540 F588 | F9554 | R540 F588 |
| F-8420 | R224 F36-42 | F9554 | R546 F148 | F5542 | R528 F072 |
| F-8420 | R466F179-180-Comm | F5542 | R528 F072 | G4730 | R522F642 |
| D-9824 | R466F175-178 | G4730 | R522F642 | D-4958 | R615F225 |
| D-9824 | R565F428 | D-4958 | R615F225 | D-4958 | R615F225 |
| D-9824 | R565F428 | F-5542 | R615F225 | F-5542 | R615F225 |
| F-8697 | R538 F210 | G-3058 | R716F89 | G-3058 | R716F89 |
| F8697 | R542 F584 | G-4730 | R 1098 F220 | G-4730 | R 1098 F220 |