

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>8909</i>	LOCATION <i>17 N - 2nd St.</i>			
DATE <i>11/13/81</i>	PURPOSE <i>Remod of Garage</i>			
ZONE <i>Multifam</i>	OWNER <i>M. Landykat</i>			
	ARCH'T <i>Basement not furnished plans</i>			
	CONT-R <i>Owner</i>			
VAL. <i>250 -</i>	STORIES	ROOMS	APTS.	SIZE

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK-REMARKS
11/25/31	<p>1st Insp. Widening of Foundation to 16" at the bottom required for 2 story Bldg. Allow Raising 3' Casework to 18" below 1st Floor Joists. Mr. Campbell Owner took out Additional Permit for finishing off flat in 1st Story.</p>
1/7/32	<p>2nd Insp. Frame " OK Mr. Campbell</p>
	<p>COMPLETE AND O.K. INSPECTOR</p>