

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. 3-2151	LOCATION 3234 - Riverside Blvd			
DATE 12/27/38	PURPOSE Gen. Repair to dwlg.			
ZONE	OWNER H. J. Huber			
	ARCH'T.			
	CONTR. Owner			
VAL. 2002	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS			ELEVATOR SHAFTS	
VENT SHAFTS			BOILER ROOMS	
OWNER'S INSPECTOR			SPRINKLER SYSTEM	
LATH			GAS VENTS	
FIRE ESCAPES			CHIMNEYS	
STAND PIPES			SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
1-4-39	2 nd Jump to road at <i>P</i>
	COMPLETE AND O. K. INSPECTOR