

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. 8892	LOCATION 1016-19th St.			
DATE 11/16/31	PURPOSE Gen Rep Fire Loss			
ZONE 2nd Class	OWNER W. G. Martin			
	ARCH'T Journal			
	CONT-R Journal			
VAL. 500 -	STORIES 2	ROOMS	APTS.	SIZE
Light Shafts		Elevator Shafts		
Vent Shafts		Boiler Rooms		
Owner's Inspector		Sprinkler System		
Lath		Gas Vents		
Fire Escapes		Chimneys		
Stand Pipes		Skylights		

DATE	CONDITION OF WORK-REMARKS
11/16/31	Made Preliminary Insp of damage by fire to Roof of 9 Story Frame Bldg. ^{OK} A.W. Campbell Told Carpenter to replace all burned Rafters, Ceiling, Gypsum Platts etc with new material.
11/27/31	2 ND / NSP. Frame for New Roof ^{OK} A.W. Campbell
12/16/31	3 RD / NSP. Int. Latr. Ceiling of 2 ND Story ^{OK} A.W. Campbell
1/26/32	4 TH / NSP. General Repairs Completed A.W. Campbell Struck cleaned up ^{OK}
1/26/32	COMPLETE AND O.K. <i>Allen W. Campbell</i> INSPECTOR.