

R335F351

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$18.00

TYPE BUILDINGS

PERMIT NO. H-8533	LOCATION 2818 - 38th Street			A-1
DATE Aug-25-72	PURPOSE General repairs to dwelling			
ZONE	OWNER Vest Huston same			
	ARCH'T			
	CONT'R same owner			
VAL. \$1,500.	STORIES	ROOMS	APTS.	SIZE
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	PHONE (O) (C) 383 5742
FORM				
JOIST				
FRAME	2-8-73	Bachato		
SHEET ROCK	2-8-73	Bachato		
FINAL				

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
1-15-73	P.I. frame - Dwg locked Lassen
1-18-73	P.t - " Dwg locked Lassen
1-25-73	P.t. frame - draft stop dropped ceiling floor windows, studs, wire for on Lassen
2-5-73	PT-frame - no job card or plan Riolo
2-8-73	
	<p>COMPLETE AND OK</p> <p style="text-align: right;">INSPECTOR</p>