

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPES I, II, III, IV, V, VI BUILDINGS

PERMIT NO. <i>70012</i>	LOCATION <i>3121 Stanton Bldg</i>
DATE <i>11/20/31</i>	PURPOSE <i>550 sq ft bank building</i>
ZONE <i>Low Res</i>	OWNER <i>H. J. Sullivan</i>
	ARCH'T
	CONT'R <i>E. D. Bowen</i>

VAL. <i>4000</i>	STORIES	ROOMS	APTS.	SIZE
---------------------	---------	-------	-------	------

Steel Tested by	Elevator Shafts
Cement Tested by	Boller Rooms
Owner's Inspector Rfcd. Conc.	Sprinkler System
	Floor Tests
Fire Escapes	
Stand Pipes	

DATE	CONDITION OF WORK—REMARKS
	COMPLETED AND O.K. INSPECTOR