

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-5478</i>	LOCATION <i>1401 - 10th</i>			
DATE <i>1/6/37</i>	PURPOSE <i>Re-roof Bldg.</i>			
ZONE <i>General Commercial</i>	OWNER <i>Carl A. Hendryson 1501 K-St.</i>			
	ARCH'T.			
	CON'TR. <i>Roof Serv. Co.</i>			
VAL. <i>25000</i>	STORIES	ROOMS	APTS.	SIZE

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
1/8/37	Re Report of 1-8-37
	Re Report of 1-8-37
	Re Report of 1-8-37
	Re Report of 1-8-37
	Re Report of 1-8-37
	Re Report of 1-8-37
	Re Report of 1-8-37
	Re Report of 1-8-37
	Re Report of 1-8-37
1/8/37	<p>COMPLETE AND O. K. <i>[Signature]</i></p> <p style="text-align: right;">INSPECTOR</p>