

**BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD**

**TYPES I, II, III, IV, V, VI BUILDINGS**

<b>PERMIT NO.</b> 6663	<b>LOCATION</b> 18 <sup>12</sup> 13 <sup>13</sup> 9 <sup>9</sup>	<b>PHONES</b> 917 E. 921-1284 1701			
<b>DATE</b> 8/1/30	<b>PURPOSE</b> Super Serv. Sta. Tire Sales room				
<b>ZONE</b> GENERAL COMMERCIAL	<b>OWNER</b> U. S. Co. 879 J. SF				
	<b>ARCH'T</b> W. S. Trassum				
	<b>CONT'R</b> Campbell Const Co 8718				
<b>VAL.</b> 18771 —	<b>STORIES</b> 2	<b>ROOMS</b>	<b>APTS.</b>	<b>SIZE</b> — 32	

<b>Steel Tested by</b>	<i>Passed by Council 7/31/30</i>	<b>Elevator Shafts</b>	
<b>Cement Tested by</b>		<b>Boiler Rooms</b>	
<b>Owner's Inspector Rfcd. Conc.</b>		<b>Sprinkler System</b>	
		<b>Floor Tests</b>	
<b>Fire Escapes</b>			
<b>Stand Pipes</b>			

DATE	CONDITION OF WORK—REMARKS
8/5/30	Partial Incep. Non Building near Bridge South. Hall of Tire Repair Bldg. Also installing 2 <sup>nd</sup> floor Joists on same. Non Mechanic old Balcony of old State Theater on site. A.W. Campbell and clearing away debris as rapidly as possible.
8/7/30	Frame inspected by R. W. Reuter
9/6/30	3 <sup>rd</sup> Incep. Int + Ext. Job OK A.W. Campbell
9/6/30	4 <sup>th</sup> Incep. Bldg. Completed A.W. Campbell
9/6/30	Issued Certificate of Occup. A.W. Campbell
"	Street cleaned up OK A.W. Campbell
9/6/30	COMPLETED AND O.K. A.W. Campbell INSPECTOR