

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

| | |
|------------------------------|---|
| PERMIT NO. <i>B-11595</i> | LOCATION <i>2918 - 9 St</i> |
| DATE <i>9/28/43</i> | PURPOSE <i>Remodel Basement of dwlg.</i> |
| ZONE | OWNER <i>Sergii Leachin</i> |
| | ARCH'T. |
| | CONTR. <i>Robert S. Morris</i> |

| | | | | |
|------------------------------|---------|-------|-------|------|
| VAL. <i>900⁰⁰</i> | STORIES | ROOMS | APTS. | SIZE |
|------------------------------|---------|-------|-------|------|

| | | | |
|-------------------|--|------------------|--|
| LIGHT SHAFTS | | ELEVATOR SHAFTS | |
| VENT SHAFTS | | BOILER ROOMS | |
| OWNER'S INSPECTOR | | SPRINKLER SYSTEM | |
| LATH | | GAS VENTS | |
| FIRE ESCAPES | | CHIMNEYS | |
| STAND PIPES | | SKYLIGHTS | |

| DATE | Gen. Con. Work CONDITION OF WORK—REMARKS |
|----------|---|
| 10/6/43 | 1 ST / HSP Forms for Basement Walls & Piers for ^{OK} Foundation. Stops under ^{OK} Directly ^{OK} AW Campbell |
| 10/25/43 | 2 ND / HSP. Frame for above ^{OK} AW Campbell |
| | |
| | |
| | |
| | |
| | |
| | <div style="display: flex; justify-content: space-between;"> COMPLETE AND O. K. INSPECTOR </div> |