

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-6891</i>	LOCATION <i>1708 - C St.</i>			
DATE <i>8/31/39</i>	PURPOSE <i>Repairs to dwlg</i>			
ZONE	OWNER <i>F. J. Agnetti</i>			
	ARCH'T.			
	CONTR. <i>John Eckert</i>			
VAL. <i>1500</i>	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK—REMARKS
9/17/37	2 ND / NSP. Frame for Reconditioning 2 Flat Blows OK A.W. Campbell
9/22/37	3 RD / NSP. INT + EXT LATH OK A.W. Campbell
	<p style="text-align: center;"> $\begin{array}{r} 6 \\ 25 \overline{) 150} \\ \underline{100} \\ 50 \\ \underline{50} \\ 0 \end{array}$ </p>
	<p>COMPLETE AND O. K. INSPECTOR</p>