

B189 7402

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD

\$5.00

TYPE BUILDINGS

PERMIT NO. F-3523	LOCATION 1320 - 39th Street A-1
DATE Mar. 22-66	PURPOSE Repair front porch of dwelling.
ZONE R-1	OWNER John Kennedy Same
	ARCH'T GI 2-5624
	CONT'R Chas. Vanina 2022-Capitol Ave.

VAL. \$500.	STORIES	ROOMS	APTS.	SIZE
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	PHONE (O) (C)
FORM				
JOIST				
FRAME				
SHEET ROCK				
FINAL	<i>4-12-66</i>	<i>J. Birbato</i>		

117
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
B-31-66	P/Bial. No plans on job Repair
	COMPLETE AND OK

INSPECTOR