

DATE	CONDITION OF WORK—REMARKS
12/17/29	Made Location Inspection of Brick Private Garage
	located in N. W. Corner of Top row of Drive;
	with brick walls on West & North line and also
	South Wall less than 6 ft from Drive OK
	H. W. Campbell
1/6/30	4 th Insp. Brick Private Garage Condition OK
	H. W. Campbell
	Street cleaned up OK H. W. Campbell
1/6/30	COMPLETED AND O.K. H. W. Campbell
	INSPECTOR