

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS				INSPECTION AREA	FINAL INSPECTIONS		
		2860 Belmar St.				1			
LEGAL DESCRIPTION				OCCUP. GR.	CONST TYPE	VAR. NO.	FIRE ZONE		
Glenbrook #3 Lot 250									
TITLE AND NAME		1/C	ADDRESS		ZIP	CITY LIC. NO.	TEL. NO.	BUILDING BY <i>Larsen</i>	DATE <i>7/29/66</i>
GEN. CONTR. Owner								ELECTRICAL BY	DATE
ELEC. CONTR.								PLUMBING BY	DATE
PLBG. CONTR.								MECHANICAL BY	DATE
MECH. CONTR.									
ARCH. ENGR.									
OWNER Besco			2777 Alvarado St., San Leandro					CERTIFICATE OF OCCUPANCY	
CONST. LOAN LENDER								ISSUED BY	DATE
BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOF CONSTR.	AREA 1st FLOOR	TOTAL AREA	C.S.D.	C.I. CASE	
-			1			1,394			
SIDE YARDS	REAR YARDS	SET BACK REQ.	USE ZONE	PARK'G REQ.	SPACES	TREES RMVD.	EXISTING BLDG'S SAME LOT	HOW USED	

NATURE OF WORK:- Const. dwelling & garage Plan 430-G

PERMIT NO. S.P. - F-3702	MICROFILM RECORD		
ISSUED BY	PLANS AND APPLICATION	REEL NO. 191	FRAME NO:- 220 TO
ISSUANCE DATE 4-6-66	INSPECTION RECORD	REEL NO. 186	FRAME NO:- 226 TO 287
VALUATION \$ 13,800.00	JOB FILE <i>Cambone</i>	REEL NO. 226	FRAME NO:- 228 TO
R.D.F. FEE \$			
S.M.I. FEE \$			
PLAN CK. FEE \$			
SEWER INCL. FEE \$			
PERMIT FEE \$ 49.00	REMARKS AND/OR VARIANCES		
\$	Dwelling		
\$			
TOTAL FEES \$			

