

Bill 7455

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$13.00

TYPE BUILDINGS

PERMIT NO. E-9600	LOCATION 1716 - F Street A-2				
DATE Feb 16-65	PURPOSE Repair termite & rot damage to dwlg.				
ZONE	OWNER Jose Guerro Same				
V 1	ARCH'T GL 8-1882				
	CONT'R Valley Termite 1617 - 18th St.				
VAL. \$1,300.	STORIES	ROOMS	APTS.	448-2911	SIZE
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	PHONE (O) (C)	
FORM					
JOIST					
FRAME	5.25.65 <i>Hammond</i>				
SHEET ROCK					
FINAL	7.21.65 <i>[Signature]</i> <i>hit</i>				

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
3-5-65	OK to Continue as is but metal string joist to outside ^{floor} walls
3-12-65	OK Joist for N-E room. Larsen
5-25-65	OK subfloor, back bedroom only. Hamman
6-14-65	OK to subfloor front room. Hamman
7-13-65	OK frame - middle bedroom. Perit
COMPLETE AND OK	INSPECTOR