

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>No. 104</i> DATE <i>6/9/31</i> ZONE	LOCATION	<i>Rest Room</i>	<i>2816-39 St.</i>
	PURPOSE	<i>Year down old & Rebuild a little larger</i>	
	OWNER	<i>Lura Riley</i>	
	ARCH'T		
	CONT-R	<i>Owner</i>	

VALU <i>See Plan Book</i>	STORIES	ROOMS	APTS.	SIZE <i>124 sq ft</i>
------------------------------	---------	-------	-------	--------------------------

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>No chg.</i> DATE <i>1-26-51</i> ZONE	LOCATION <i>2816-39 Street</i> PURPOSE <i>Repair damage</i> OWNER <i>V. Cole</i> ARCH'T. CONTR. <i>Clune</i>
--	--

VAL. \$ <i>90</i>	STORIES	ROOMS	APTS.	SIZE
-------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
	<p data-bbox="331 824 459 864">COMPLETE AND O. K.</p> <p data-bbox="1187 840 1321 860">INSPECTOR</p>