

B151 7863

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD

\$10.00

TYPE BUILDINGS

| | | | | | |
|----------------------|---------|---|-------|-----------------|---------------|
| PERMIT NO. E-8149 | | LOCATION 1317 - 23rd Street A-2 | | | |
| DATE Aug 17-64 | | PURPOSE Repair fire damage to dwlg. | | | |
| ZONE | | OWNER G. R. Cassady 1717 $\frac{1}{2}$ -N St. | | | |
| | | ARCH'T | | | |
| | | CONT'R Owner Same GI 8-7940 | | | |
| VAL \$800. | | STORIES | ROOMS | APTS. | SIZE |
| INSP. | DATE | BLDG. TYPE | | OCCUPANCY GROUP | PHONE (O) (C) |
| FORM | | | | | |
| JOIST | | | | | |
| FRAME | | | | | |
| SHEET ROCK | | | | | |
| FINAL | 9-23-64 | Hammond | | | |

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|------|--|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | COMPLETE AND OK INSPECTOR |