

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>No Charge PERMIT</i>	LOCATION <i>1317-24^{7A} ST.</i>
DATE <i>APR. 22 1931</i>	PURPOSE <i>Misc Partitions, 3' Change location of Sink & make repairs</i>
ZONE <i>Mulhalla Family</i>	OWNER <i>Mrs. MILDRED WATTS</i>
	ARCH'T <i>In rear porch & steps</i>
	CONT-R <i>F. E. DOLSE</i>
VAL. <i>90⁰⁰</i>	STORIES
	ROOMS
	APTS.
	SIZE

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK-REMARKS
4/25/31	Partial Frame Jap In alterations to partition and rear porch + steps.
	Will take out Pay Permit if Council decides to install bath room. A.W. Campbell
	COMPLETE AND O.K. INSPECTOR