

R-ES

Lot 23

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

F528-532

Richland

**TYPE BUILDINGS** \$33.50

PERMIT NO. -5250	LOCATION 5733-71 St. - 11/4
DATE Apr. 12, 60	PURPOSE Const dwelling and garage
ZONE R-1	OWNER Ray Cisneros 5725-71 St.
	ARCH'T CONT'R Wilmar Homes 5601 Mananita ED 2-6230

VAL. \$11,500.	STORIES 1	ROOMS 6	APTS.	430 Gar.. SIZE 1166 Sq.ft.
----------------	--------------	------------	-------	-------------------------------

INSP.	DATE	INSPECTOR
FORM	4-26-60	Shumway
JOIST	C	
FRAME	5-28-60	Fuller
LATH	6-10-60	Fuller
FINAL	8-15-60	Calloway

DATE	SPECIAL CONDITIONS OF WORK—REMARKS
4-25-60	P.T. Plumbing ditches not backfilled. No gravel in place. Shumway
5-24-60	P.T. No spark arrester. Fuller
8-1-60	P.T. No driveway - Calloway
8-9-60	P.T. Range hood vent not properly installed and vents to roof. Barbato.
8-10-60	P.T. exhaust fan roof as Kitcher Calloway
	<div data-bbox="338 989 488 1047" data-label="Text">COMPLETE AND OK</div> <div data-bbox="1333 1018 1492 1047" data-label="Text">INSPECTOR</div>