

BUILDING DIVISION--BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>9962</i>	LOCATION <i>1021 - 40th St.</i>
DATE <i>9-30-32</i>	PURPOSE <i>No. roof dwelling - Asphalt</i> PHONES <i>via angles</i>
ZONE <i>1 - 30-32</i>	OWNER <i>E. Hendrickson</i>
	ARCH'T
	CONT-R <i>Cahill Roofing Company</i>

VAL. <i>9,150⁰⁰</i>	STORIES	ROOMS <i>11</i>	APTS. <i>7</i>	SIZE <i>7</i>
--------------------------------	---------	--------------------	-------------------	------------------

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK--REMARKS
	<p data-bbox="363 812 516 861">COMPLETE AND O. K.</p> <p data-bbox="1156 837 1318 861">INSPECTOR</p>